



SUPPORT LOCAL AND LEAVE US A REVIEW

If you are happy with Regional Ramp's services, please help us help others by leaving us a Google review. Small businesses can have a big impact when the community they serve supports them. Thank you for taking the time to support a local business.



You can Google **regional ramp** and click the **review** button.

OR

Scan this code with your camera phone to leave a Google review on your experience.



RAMP CLEANING CARE AND MAINTENANCE

Our ramps are manufactured with a dual-direction ribbed surface, which provides great traction under normal conditions. Environmental hazards like mud, leaves, snow and ice can compromise traction, so please follow our suggestions for care and maintenance.

Year-round care

Keep all surfaces clear of dirt, leaves or debris by sweeping with a thick-bristled push broom, leaf blower, garden hose or power spray, as required.

Winter maintenance

In winter, the ramp can become slippery if the ribs fill with snow and ice. Keep all surfaces clear of ice and snow buildup by shoveling snow with a plastic snow shovel or sweeping with a thick-bristled push broom.

Use non-corrosive ice melt* when it gets icy. If you are unsure if an ice melt is corrosive, select a formula that is safe for pets. The primary ingredient that is safe to use on an aluminum ramp is magnesium chloride or a calcium-magnesium-based compound.

For wheelchair and walker users, consider traction wheelchair tires, also known as snow tires, for better traction through snow and on uneven surfaces.

Come spring, the thaw can heave or depress the ground beneath the ramp on both grass and hard surfaces, including patio stones and interlocking brick. If you notice any abnormal changes in the ramp surface (pitching, bouncing, drops, uneven edges) please call us for a safety adjustment.

* Please DO NOT use any regular road salt (rock salt) ice product. It will damage the aluminum ramp and may compromise safety.

Questions? Contact us:

regionalramp.com consult@regionalramp.com (613) 262-1881